

# SAFETY VALVE INSPECTION & TEST CERTIFICATE




<b>Certificate Number</b>	SVC 0090-16
<b>EF Number</b>	327268

<b>Customer Name</b>	Statoil Petroleum AS
<b>Customer Address</b>	Mongstad Raffineri Hovedlager, Varemottak Mongstad 5954 Norway
<b>Customer Reference</b>	4590016865

### Safety Valve Information

Test Date	Fender Serial Number	Fender Size	Safety Valve Serial Number	Internal Or External	Test Standard	Valve Set At
26/07/2016	AY34M	3.3 x 6.5	B2275P	RPS23	Good	1.8Bar

<b>Overhauled and Tested By</b>	Terry Crane – Fender Engineer
---------------------------------	-------------------------------

<b>Signature</b>	
------------------	---

<b>Next Inspection/Test Due</b>	25/07/2019
---------------------------------	------------

*Yokohama recommend inspecting the appearance and cleaning the safety valve (if necessary) every second year, with a full safety valve overhaul including detaching the valve within the third year period (not to exceed 36 months) – Fendercare Marine can offer this service within the third year to ensure certification validity. It is recommended that the planning of this service takes place from the start of the second year to ensure completion prior to the expiration date. Please be aware that your public liability insurance may be invalidated should this service not be carried out.*

***This test has been carried out in accordance with Yokohama's recommendations and by fender care, a manufacturer approved repair centre.***

# SAFETY VALVE INSPECTION & TEST CERTIFICATE




<b>Certificate Number</b>	SVC 0091-16
<b>EF Number</b>	327268

<b>Customer Name</b>	Statoil Petroleum AS
<b>Customer Address</b>	Mongstad Raffineri Hovedlager, Varemottak Mongstad 5954 Norway
<b>Customer Reference</b>	4590016865

### Safety Valve Information

Test Date	Fender Serial Number	Fender Size	Safety Valve Serial Number	Internal Or External	Test Standard	Valve Set At
27/07/2016	AY35M	3.3 x 6.5	B3419C	RPS23	Good	1.8Bar

<b>Overhauled and Tested By</b>	Terry Crane – Fender Engineer
---------------------------------	-------------------------------


<b>Signature</b>	
------------------	---

<b>Next Inspection/Test Due</b>	26/07/2019
---------------------------------	------------

*Yokohama recommend inspecting the appearance and cleaning the safety valve (if necessary) every second year, with a full safety valve overhaul including detaching the valve within the third year period (not to exceed 36 months) – Fendercare Marine can offer this service within the third year to ensure certification validity. It is recommended that the planning of this service takes place from the start of the second year to ensure completion prior to the expiration date. Please be aware that your public liability insurance may be invalidated should this service not be carried out.*

***This test has been carried out in accordance with Yokohama's recommendations and by fender care, a manufacturer approved repair centre.***

Fendercare Marine Limited  
Enterprise House, Harveys Lane, Seething, Norfolk, NR15 1EN, United Kingdom  
T +44 1508 482691 F +44 1508 482710 E sales@fendercare.com www.fendercare.com



Registered No 3075910

# SAFETY VALVE INSPECTION & TEST CERTIFICATE




<b>Certificate Number</b>	SVC 0093-16
<b>EF Number</b>	327268

<b>Customer Name</b>	Statoil Petroleum AS
<b>Customer Address</b>	Mongstad Raffineri Hovedlager, Varemottak Mongstad 5954 Norway
<b>Customer Reference</b>	4590016865

### Safety Valve Information

Test Date	Fender Serial Number	Fender Size	Safety Valve Serial Number	Internal Or External	Test Standard	Valve Set At
26/07/2016	AY37M	3.3 x 6.5	B3419B	RPS23	Good	1.8Bar

<b>Overhauled and Tested By</b>	Terry Crane – Fender Engineer
---------------------------------	-------------------------------

<b>Signature</b>	
------------------	---

<b>Next Inspection/Test Due</b>	25/07/2019
---------------------------------	------------

*Yokohama recommend inspecting the appearance and cleaning the safety valve (if necessary) every second year, with a full safety valve overhaul including detaching the valve within the third year period (not to exceed 36 months) – Fendercare Marine can offer this service within the third year to ensure certification validity. It is recommended that the planning of this service takes place from the start of the second year to ensure completion prior to the expiration date. Please be aware that your public liability insurance may be invalidated should this service not be carried out.*

***This test has been carried out in accordance with Yokohama's recommendations and by fender care, a manufacturer approved repair centre.***

Fendercare Marine Limited  
Enterprise House, Harveys Lane, Seething, Norfolk, NR15 1EN, United Kingdom  
T +44 1508 482691 F +44 1508 482710 E sales@fendercare.com www.fendercare.com

James Fisher and Sons plc  
Member of the James Fisher Group



Registered No 3075910

# SAFETY VALVE INSPECTION & TEST CERTIFICATE




<b>Certificate Number</b>	SVC 0092-16
<b>EF Number</b>	327268

<b>Customer Name</b>	Statoil Petroleum AS
<b>Customer Address</b>	Mongstad Raffineri Hovedlager, Varemottak Mongstad 5954 Norway
<b>Customer Reference</b>	4590016865

### Safety Valve Information

Test Date	Fender Serial Number	Fender Size	Safety Valve Serial Number	Internal Or External	Test Standard	Valve Set At
27/07/2016	AY36M	3.3 x 6.5	B3419H	RPS23	Good	1.8Bar

<b>Overhauled and Tested By</b>	Terry Crane – Fender Engineer
---------------------------------	-------------------------------

<b>Signature</b>	
------------------	---

<b>Next Inspection/Test Due</b>	26/07/2019
---------------------------------	------------

*Yokohama recommend inspecting the appearance and cleaning the safety valve (if necessary) every second year, with a full safety valve overhaul including detaching the valve within the third year period (not to exceed 36 months) – Fendercare Marine can offer this service within the third year to ensure certification validity. It is recommended that the planning of this service takes place from the start of the second year to ensure completion prior to the expiration date. Please be aware that your public liability insurance may be invalidated should this service not be carried out.*

***This test has been carried out in accordance with Yokohama's recommendations and by fender care, a manufacturer approved repair centre.***

