

Inspection – Wheel Loader

Item	CAT 950H - 2008	Chassinr	CAT0950HJN1A02300	Hours	4032
------	-----------------	----------	-------------------	-------	------

WHAT IS INSPECTED WHAT WE LOOK FOR ✓ COMMENT


VISUAL INSPECTION

CHASSI	Damage, wear	✓	
LOADER BOOM	Damage and old repairs	✓	
BUCKET	What is included, wear	✓	3500m3 Cat original Model: 334-4403
CYLINDERS	Damage & leakage	✓	
WAIST	Leakage	✓	
BUSHINGS & PINS	Play, greased, nipples	✓	
HYDRAULIC HOES	Damage, wear, leakage	✓	
WHEELS	Damage & wear	✓	No damages, see picture for wear
WINDOWS	Damage, cracks	✓	Chip in upper right corner, behind rearview mirror
ENGINE DEPARTMENT	Leakage, damage to cables and hoses	✓	
COOLER	Damage on fan and fins	✓	
BATTERY	Corrosion, attachment, date	✓	

TEST DRIVE

START	Quick or heavy start, heavy smoking	✓	
ERROR MESSAGES	Error lights or messages	✓	
LIGHTS	Function	✓	
AC	Function	✓	
PARKINGBREAK	Working or not	✓	
WAIST	Play on the bushings	✓	
GEARS	Trying all gears	✓	
MOVING MATERIAL	If possible, test the machine under heavy load	✓	Slow in the hydraulic before the oil is warm.

Notes: Cleaned and inspected in our workshop, is available for testdriving

Inspected by:  Date: 2020-02-12